


Ø FRACTIONNELS / INCH Ø

HARD-LINE / 40

6
pièces
pieces


Basic



Univ.: 20.1926
Weldon: 20.1909

Ø 2x5/8", 2x13/16", 2x15/16"
2 pointes d'éjection / 2 ejector pins

Basic plus




Univ.: 20.1478
Weldon: 20.1978

Ø 9/16", 5/8", 3/4", 13/16", 15/16", 1.1/16"
2 pointes d'éjection / 2 ejector pins

12
pièces
pieces


Profi



Univ.: 20.1927
Weldon: 20.1911

Ø 4x5/8", 4x13/16", 4x15/16"
2 pointes d'éjection / 2 ejector pins

Profi plus



Univ.: 20.1928
Weldon: 20.1914


Ø 2x9/16", 2x5/8", 2x3/4", 2x13/16", 2x15/16", 2x1.1/16"
2 pointes d'éjection / 2 ejector pins

100TCT

HARD-LINE / 55

6
pièces
pieces


Basic



Univ.: 20.1929
Weldon: 20.1915

Ø 2x13/16", 2x15/16", 2x1.1/16"
2 pointes d'éjection / 2 ejector pins

Basic plus




Univ.: 20.1479
Weldon: 20.1979

Ø 5/8", 11/16", 3/4", 13/16", 15/16", 1.1/16"
2 pointes d'éjection / 2 ejector pins

200TCT

12
pièces
pieces

Profi



Univ.: 20.1931
Weldon: 20.1916

Ø 4x13/16", 4x15/16", 4x1.1/16"
2 pointes d'éjection / 2 ejector pins

Profi plus



Univ.: 20.1932
Weldon: 20.1917

Ø 2x5/8", 2x11/16", 2x3/4", 2x13/16", 2x15/16", 2x1.1/16"
2 pointes d'éjection / 2 ejector pins