


Ø MÉTRIQUES / METRICØ

**BLUE-DRILL LINE 30**

**100BLU**

**6**  
pièces  
pieces

**Basic**



Univ.: 20.1958  
Weldon: 20.1950

Universel  
Ø 2x16, 2x18, 2x22 mm  
2 pointes d'éjection / 2 ejector pins

Weldon  
Ø 2x14, 2x18, 2x22 mm  
2 pointes d'éjection / 2 ejector pins

**Basic plus**




Univ.: 20.1348  
Weldon: 20.1325

Ø 14, 16, 18, 20, 22, 26 mm  
2 pointes d'éjection / 2 ejector pins

**12**  
pièces  
pieces

**Profi**




Univ.: 20.1959  
Weldon: 20.1951

Universel  
Ø 3x14, 3x18, 3x20, 3x22 mm  
2 pointes d'éjection / 2 ejector pins

Weldon  
Ø 3x12, 3x14, 3x18, 3x22 mm  
2 pointes d'éjection / 2 ejector pins

**Profi plus**



Univ.: 20.1960  
Weldon: 20.1952

Universel  
Ø 2x14, 2x16, 2x18, 2x20, 2x22, 2x26 mm  
2 pointes d'éjection / 2 ejector pins


Weldon  
Ø 2x12, 2x14, 2x16, 2x18, 2x20, 2x22 mm  
2 pointes d'éjection / 2 ejector pins

**BLUE-DRILL LINE 55**

**200BLU**

**6**  
pièces  
pieces

**Basic**



Univ.: 20.1961  
Weldon: 20.1954

Ø 2x14, 2x18, 2x22 mm  
2 pointes d'éjection / 2 ejector pins

**Basic plus**




Univ.: 20.1349  
Weldon: 20.1328

Ø 14, 16, 18, 20, 22, 26 mm  
2 pointes d'éjection / 2 ejector pins

**12**  
pièces  
pieces

**Profi**




Univ.: 20.1962  
Weldon: 20.1955

Universel  
Ø 3x14, 3x18, 3x20, 3x22 mm  
2 pointes d'éjection / 2 ejector pins

Weldon  
Ø 4x14, 4x18, 4x22 mm  
2 pointes d'éjection / 2 ejector pins

**Profi plus**



Univ.: 20.1963  
Weldon: 20.1956

Ø 2x14, 2x16, 2x18, 2x20, 2x22, 2x26 mm  
2 pointes d'éjection / 2 ejector pins