

Ø MÉTRIQUES / METRIC Ø

HARD-LINE / 40

100TCT

6
pièces
pieces

Basic




Univ.: 20.1918
Weldon: 20.1901

Universel
Ø 2x18, 2x22, 2x26 mm
2 pointes d'éjection / 2 ejector pins

Weldon
Ø 2x14, 2x18, 2x22 mm
2 pointes d'éjection / 2 ejector pins

Basic plus




Univ.: 20.1329
Weldon: 20.1336

Universel
Ø12, 14, 16, 18, 22, 26 mm
4 pointes d'éjection / 4 ejector pins

Weldon
Ø12, 14, 16, 18, 20, 22 mm
4 pointes d'éjection / 4 ejector pins

12
pièces
pieces

Profi




Univ.: 20.1919
Weldon: 20.1902

Universel
Ø 3x14, 3x18, 3x22, 3x26 mm
4 pointes d'éjection / 4 ejector pins

Weldon
Ø 4x14, 4x18, 4x22 mm
4 pointes d'éjection / 4 ejector pins

Profi plus



Univ.: 20.1921
Weldon: 20.1903

Universel
Ø 2x12, 2x14, 2x16, 2x18, 2x22, 2x26 mm
4 pointes d'éjection / 4 ejector pins


Weldon
Ø 2x12, 2x17, 2x16, 2x18, 2x20, 2x22 mm
4 pointes d'éjection / 4 ejector pins

HARD-LINE / 55

200TCT

6
pièces
pieces


Basic



Univ.: 20.1922
Weldon: 20.1905

Ø 2x14, 2x18, 2x22 mm
4 pointes d'éjection / 4 ejector pins

Basic plus




Univ.: 20.1338
Weldon: 20.1339

Universel
Ø12, 14, 16, 18, 22, 26 mm
4 pointes d'éjection / 4 ejector pins

Weldon
Ø14, 16, 18, 22, 26 mm
4 pointes d'éjection / 4 ejector pins

12
pièces
pieces

Profi



Univ.: 20.1923
Weldon: 20.1906

Ø 3x14, 3x18, 3x22, 3x26 mm
4 pointes d'éjection / 4 ejector pins

Profi plus



Univ.: 20.1924
Weldon: 20.1907

Ø 2x14, 2x16, 2x18, 2x20, 2x22, 2x26 mm
4 pointes d'éjection / 4 ejector pins